

# Pocket IR Thermometer


Wide range Non-contact InfraRed Thermometer with Laser pointer

## Features:

- Wide temperature range from -58°F to 518°F without contact
- Built-in laser pointer to improve aim
- °F/°C switchable
- Fixed emissivity (0.95) covers 90% of surface applications
- 6:1 field of view
- Visual overrange indicator
- Data Hold and Max Hold
- Pocket size meter
- Complete with two AAA batteries

## Applications:

- Measure surface temperature of objects which are difficult to reach or unsafe to contact
- Measure hot spots in electrical panels and equipment
- In-process temperature measurements



Specifications	
Range:	-58 to 518°F or -50 to 270°C
Accuracy:	±2.5% of reading + 3°F/2°C
Resolution:	1°F/°C
Emissivity:	0.95 fixed
Power:	2 x AAA batteries
Field of view:	6:1 (at 6" distance measure 1" target)
Dimensions:	3.7x2x1" (94x51x25mm)
Weight:	2.7oz (76g)



Refrigeration



HVAC



Troubleshooting  
for hot spots

## Ordering Information:

IR201 .....Pocket IR Thermometer